UNCLASSIFIED

AD NUMBER

AD512691

CLASSIFICATION CHANGES

TO:

unclassified

FROM:

confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

DoD Controlling Organization: Department of the Army, Office of the Adjutant General, Washington, DC 20310.

AUTHORITY

GDS per DoD 5200.1-r; Adjutant General's Office [Army] ltr dtd 29 Apr 1980



DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

AGDA (M) (12 Nov 70)

FOR OT UT 702215

25 November 1970

SUBJECT: Operational Report - Lessons Learned, Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970 (U)

SEE DISTRIBUTION

i. Subject report is forwarded for review and evaluation in accordance with paragraph 4b, AR 525-15. Information of actions initiated as a result of subject report should be forwarded to ACSFOR OT UT within 90 days of receipt of covering letter.

2. Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

i Incl as

Enneth G. Nacklam

KENNETH G. WICKHAM Major General, USA The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

US Army Materiel Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Armor School

US Army Aviation School

US Army Combat Surveillance School

US Army Electronic Warfare School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

US Army Ordnance School

US Army Transportation School

Regraded unclassified when separated from classified inclosure.

CONFIDENTIAL

BEST AVAILABLE COPY

DISTRIBUTION (Cont'd)

Copies furnished: Office, Chief of Staff, US Army Deputy Chiefs of Staff Chief of Research and Development Assistant Chiefs of Staff Chief of Engineers OSD(SA) Assistant for Southeast Asia Forces Office, Director of Defense Research & Engineering Office of the Joint Chiefs of Staff Commanding Generals

US Army Electronics Command

US Army Weapons Command

US Army Flight Training Center

Deseret Test Center III Corps, ATTN: Director, Project MASSTER Deputy Chief of Staff, Air Force, Plans & Operations Commandant of the Marine Corps USAF Air Ground Operations School The Air University Library Defense Documentation Center USAF Project RAND Commanding Officers

US Army Limited War Laboratory

US Army Logistics, Doctrine Systems & Readiness Agency

US Army Aviation Test Activity

US Army Mobility Equipment Research & Development Center

DEFATHENT OF THE ADMY
HEADQUARTERS 15T AVIATION RESGALE
APO See Francisco 96384

I.VB.OC-O

-

15 May 1970

SUBJECT: Operational Report-Leanons Learned for Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970, RCS CSF07-65 (72) (U)

EZ DISTRIBUTION

1. (0) Operations: Significant Activities

- A. Comand
- (1) The lat Aviation Brigade mission of providing effective and responsive Gray Cviction support to US, GAT and FRMAP ground clements remained unchanged.
- (2) Changes in Key Staff Personnel The following changes were made it key staff personnel during the quarter.
 - (a) Chief of Staff:

CCL Jack M. Tumlinson, IK, 170 Jerry M. Bunyard, FA,



1 Pab 70 - 16 Pcb 70 17 Pub 70 -

(b) Secretary General Staffs

MAJ 100% G. Marks, IX, MAJ Thilip E. Courts, N.

1 705 70 - 16 755 70 17 705 70 -

- (3) The operation of 1st aviation Brigado units is shown in the Organization Chart at Inclosure 1 and the Station List at Inclosure 2.
 - b. 51/10
 - (1) Broakdown of Aviators
 - (a) Commissioned Officers 1716
 - (b) Warront Officers , 2536
 - (c) Total 4252

FOR OT LT 702215 Inclosure

CONFIDENTIAL

SOCIAMINE AFRE 12 YEARS.

AVB/.GC=O

SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970, RCS CSFCR-65 (R2) (U)

(2) Breekdown of Officers by Brench

Inf	_	645
/Jrm	-	253
AD	-	63
F/	_	376
Sig	_	123
Engr	_	161
AGC	_	17
TC	-	137
G:	-	. 11
Chem	-	3
Ord	-	19
MI	-	24
FC	•	Ó
MP	-	7
J.G	_	2
Chap	_	19
MEDS	_	53
WAC	_	٥
	-	
MC	-	<u>2479</u>
TOT AL		4392
	-	

(3) Brigade Strength. The strength of the 1st Aviation Brigade as of 30 April 1970 was as follows:

	1	SSIGNEI	<u> </u>	<u> ett</u>	ACHED	
	OFF	MO	El:	<u>off</u>	WO	EM
12th Avn Gp 17th Avn Gp 164th Avn Gp 165th Avn Gp 212th Avn En HIC 1st Avn Bde	528 617 410 125 124 50	807 822 678 67 116 21	5081 5980 4506 1436 1155 210	0 5 26 0 0	0 3 12 0 0	0 41 233 0 0
TOTALS .	1854	2571	18368	31	15	274

INCL

2

WB/CC-0
SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

(4) Recommendation for Awards. The following is a report of actions taken on all awards recommendations received by this Headquarters during the period 1 Pebruary 1970 through 30 April 1970:

locard	Recaived	Processed	Approved
MH DSC DSH SS LOH DFC SM BSM**V** BSM AM**V** AM /IRCOH**V** /IRCOM PH	1 0 80 22 798 33 108 1519 846 13486 268 4538 333	1 1 0 77 22 737 33 105 1170 805 13133 211 3941 3941	0 0 77 9 737 33 105 1170 805 13133 211 3941 333
TOTALS	22033	20569	20554

(5) Orders Published. Orders published by Headquarters, 1st /viction Brigade, broken down by month, are as follows:

MONTH	SPECIAL ORDERS	LETTER ORDERS	GENERAL ORDERS
February March April	28 31 30	46 70 <u>64</u>	610 745 984
TOTILS	89	180	2339

(6) R&R Data. During the period 1 February 1970 through 30 :pril 1970, a total of 5113 R&R allocations were received by this Headouarters. Of this number, 4682 were utilized. The following is a utilization breakdown by month:

Month	Allocations Received	/11 ocations Used	Percent of Utilization
Pebruary Harch April	1688 1840 <u>1585</u>	1605 1648 <u>1429</u>	95.1% 89.6% 90.2%
TOTALS	5113	4682	91.6%

INCL

AVENCE: Operational Report-Lessons Learned for Hoolquarters, 1st Aviation Brigado, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

(7) Applications Received. The following reflects officer applications/
appointments received by month for the period 1 February 1970 through
30 April 1970:

	RIFIE	Mill	1PR
OCS WO Direct Com RA	0 0 1 4	0 1 7 	3 0 1 7
TOTALS	5	15	11

. c. C2

Personnel Security Investigative Actions

(1)	Requests for Backgrand Investigation.	19
(2)	Requests for verification of Background Investigations:	215
(3)	Requests for National Agency checks:	51
(4)	Requests for varification of National Acomey Checks:	105
(5)	Requests for verification of Entrance Mat'l Amoney Checks:	82
(6)	Total PSI Actions:	472

(7) Of these 472 PSI Actions, 398 were completed and 74 are pending.

4. <u>G3</u>

- (1) HHC, 1st Aviation Brigade is currently operating under MTOE 01-66G, dated November 1969. This MTOE is inadequate for efficient operation of the headquarters. In early May, a revised MTOE will be submitted which will provide a headquarters organization capable of administering to the needs of the Brigade which currently has over 24,000 personnel assigned.
- (2) Reorganization of the 273d Aviation Company (Heavy Helicopter) and the 355th Aviation Company (Heavy Helicopter) have not been completed due to the lack of a detailed MTOE change. This change will provide paragraph and line numbers for additional personnel spaces that result from deactivation of supporting transportation detachments. Attempts are being made to obtain the detailed MTOE change from USARPAC.

AVBLICC-0

SUBJECT: Operational Report-Lessons Learned for Rendeuerters, let Aviation

Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (5) The following organizational changes were initiated during the reporting period:
- (a) The 314th Lyintion Detrehment (Divisional) was detached from the 1st Infentry Division and attached to 12th Lyintion Group (Combat), effective 11 February 1970.
- (b) The 317th Aviation Detachment (Divisional) was detached from the 1st Infantry Division and attached to the 12th Aviation Group (Combat), effective 17 February 1970.
- (c) The 319th Aviation Detrehment (Divisional) was detrehed from the 1st Infantry Division and attached to the 165th Eviation Group (Combat), effective 20 February 1970.
- (d) The 325th Aviation Detuchment (Divisional) was detached from XXIV Corpo and advanted to the 212th Aviation Bettalion (Combat), effective 27 Harch 1970.
- (a) The 360th Aviation Detrehment (Divisional) was detrehed from the 4th Infantry Division and attached to the An Khe Airfield Command offective 27 lbreh 1970.
- (f) D Proop, 1/4 Cavalry, 1st Infantry Division was redesignated C Proop (Mir), 16th Cavalry and assigned to the 1st Aviation Drigade on 20 Threh 1970. On 27 Warch 1970 the unit was reassigned to the 12th Lviation Group (Combat). On 5 Lpril 1970 the troop was reassigned to the 164th Lviation Group (Combat), and stationed at Soc Prang.
 - (4) Operations:
- (a) The VMLF Improvement and Modernization (IMI) program has been agreed upon by the 1st Aviation Brigade, USARV, 7th US Air Force and the Victnamese Air Force (VMAF). Publication of the final copy of the VMAF IMI Plan is expected in the May June time frame.
- (b) The plan details the turnover of eight assemble helicopter companies and one assemble support helicopter company to the VMAF during the period September 1970 Which 1971. May points of the program are:
- 1. This pilots trained at the US Army Aviation School will serve 90 days OJT with an assault helicopter company upon return to Vietnam from COMUS. Thenever possible, VMAP pilots will train with the units that are programmed for turnover.
- 2. A total of 224 VNAF evintors are scheduled to be trained under the OJT program. The first four VNAF graduating classes from COMUS are expected to total 214 aviators. The graduation dates for these classes are 25 June, 7 July, 21 July and 4 Aug 1970. OJT training is to begin 15 July 1970.

AVRIGO-0
SUBJECT: Operational Report-Leasons Learned for Headquarters, 1st Liviation
Brigade, Period Ending 50 April 1970, RCS CSFCR-65 (R2) (U)

- 2. The assault helicopter companies scheduled for VMAF conversion at Bien Hoa and Soc Frang will also term over the facilities they now occupy.
- 4. For a period of 90 days after the activation of each VIIF Squaren, the 1st Aviation Brigade will provide selected operations order personnel to remain with the newly activated squadrons to assist the units in becoming operationally ready. These personnel will be under the operational control of an Air Force Advisory Team Chief. The composition of the codes is as follows:
 - 1 Operations Officer
 - 2 Instructor Pilots
 - 11 Empariement Aircraft Communication (A minimum of two will be gunshi, Linewaft Communication)
- 5. For a period of 75 days (activation day / 15 to sufficient / 90) the lst Aviation Brighds will provide selected maintenance entire personnel to remain with the newly activated squadrons to assist the units in becoming operationally ready. These personnel will also be under the operational control of the Air Force Advisory Form Chief. The composition of the maintenance coder is as follows:
 - 1 Maintenance Officer
 - 1 Maintenance Supervisor
 - 11 Crew Chiefs
- 6. Each assoult helicopter company scheduled for turnover will provide maintenance OJT for selected VNAF personnel. This training period will begin 60 days before activation day and last for 30 days. OJT will be provided for the following personnel:
 - 1 Maintenence Officer
 - 1 Line Chief
 - 1 Engine Mechanic
 - 1 Bloctmicim
 - 10 Helicopter Mechanics
- (c) The program is proceeding according to pless and no time so thacks are unticipated.

AVRIGO-0

SUBJECT: Operational Report-Lessons Learned for Headquarters, let Lyintion Brigade, Period Ending 30 Lyril 1970, RCS CSFOR-65 (R2) (U)

(5) Training.

(a) The lat Aviation Brigade continues to use all available sources of in-country training to maintain operational readiness at all levels of command. In-country training is essential to augment training provided by CONUS bases. The following data provides a recepitulation of the training quotas allocated to subordinate units during the reporting period:

	COURSE	<u> </u>
_	The Army Aviation Refresher Training School (AARES), (Airframe, engine, technical inspector and armment courses for all helicopters utilized in Vietnam (except CR-54), the CH-47 Maintenance Supervisor Course and CH-47 SL3 and Speed Trim Maintenance Course.)	244
<u>2</u> •	USLEW conducted aviator transition and maintenance courses:	
	AE-1G	39
	CH-6	26
	OII-58	46
3.	UI-1 IP/SIP School	26
<u>4</u> •	Jungle Environmental Survival School	13
5•	PACIF Idfe Support School	20
<u>6</u> .	Doppler Training Course	5
1.	XI-35 Maintenance	44
<u>8</u> .	USANF 1st Signal Brigade Schools	_4
	COLT CALL	467

- (b) The following school changes occurred:
- 1. The CH-47 SAS and Speed Trim Maintenance Course was terminated.

AVRAGC-O
SUBJECT: Operational Report-Liscons Learnel for Handquarters, 1st Aviation
Brigado, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- 2. The value of attendance at the Jungle Environmental Survival Praining School (JEST), a two day survival communicated by the US Mavy in the Philippines, was determined to be marginal in view of the time and costs involved. A traveling training team accomplishes necessary survival training for units affected. Eviators continue to attend the JELF Pacific Life Support School (PLSS) in Okinewa on TDY status from USAW and the USAF Jungle Survival School (JSS) at Clark LFB, Philippines on route to RVII from CONUS.
- 3. The AARTS closed 17 Lpril 1970 in order to move from Vung Tou to Phm Loi. The school will reopen not later than 1 June 1970.
- 4. The 1st Aviation Brigade UH-1 TP/STP school was expended to accommodate students from other USARV units beginning in March 1970. The course includes 32 hours of ground school and 30 hours of flying. All amergency procedures are studied and practiced in detail to include touchdays autorotations, lew level autorotations, tail rotor failure landings to the ground and hydraulic failure landings to the ground.
- (c) There were no UN-1 evictor transition programs a custod by 1st aviation Brigale for Republic of Vietnam and Republic of 1960 pilots during this period. That Army evictors continue to fly with US pilots under the terms of a Menorandum of Understanding between CG, 1st Aviation Brigade and CG, Reval That Army Volunteer Force (RTAVF), dated 4 January 1976.
- (d) Two Australian Army Aviators rated in the UN-1 are flying operational missions with US aviators in the 3/17th Air Covelry Squadron.
- (a) Eleven Australian Many pilots continue to fly with the 135th Assault Helicopter Company.
- (f) This Headquarters initiated a combat evaluation of the OH-58 in the scout rele. The purpose is to determine the suitability of the OH-58 when used in a scout rele. The combat evaluation will be conducted over a ninety day period. C Troop 3/17th Air Cavalry Equadron was tasked to conduct the evaluation. The test is continuing and the first monthly report will be forwarded to this Headquarters by 10 May 1970. Initial reports indicate that the OH-58 is performing efficiently in the scout rele.
- (g) The 165th Aviation Group (Combat) is training Civil Service employees of the Directorate of Civil Aviation (DCi), RVE, to perform as air traffic controllers. Seven controllers have been trained with six receiving a fully qualified rating to handle heavy traffic (A rating) and one qualified to handle moderate traffic (B rating).
- (h) The 1st Aviation Brigade has assumed responsibility for all of the aviation related New Equipment Training Torms (NETT) in Victneme. This Headquarters programmed the movement of the NETTs to include all equipment and personnel. New facilities will be provided for the NETT at Di in-

AVBAGC-0

SUBJECT: Operational Report-Lessons Learned for Herdquarters, 1st Aviation Brigade. Period Ending 30 April 1970, RCS CSFOR-65 (RZ) (U)

(i) A detachment of the 5 th Utility Airplane Company in support of JUSPAO and a platoon of the Command Airplane Company were moved from Tan Son Muthair Base to Long Thanh North. This was in support of the effort to reduce the number of US personnel in the Saigon area and to consolidate units to facilitate better maintenance and circuaft scheduling.

a. GH

- (1) Sufficient Model 801 tail rotor hub assemblies for Ah-10 and IH-1 type aircraft arrived in RVN in February to replace the defective Model 701 assemblies. The change over installation was 90% complete as of 30 Arr 70.
- (2) The CH-58A circreft infusion program for the Brigado, which began on 29 Jan 70, reached a density of 62 by 30 April 1970. This accolerated program craitted the redistribution of the UK-1D/H aircraft assets into assult holicoptor companies and other thatical units. The use of the CH-58A circraft in CH-47 and CH-54 companies has eliminated the use of cargo helicopters for administrative and limited purposes.
- (3) The unauthorized modification of armamont subsystems became a problem area during mid-March, in that 1st Aviation Brigade units were not complying with existing regulations prohibiting the modification of large equipment.

 Armament inspectors from the Brigade and 34th General Support Broup personnel visited all units of the Brigade to enforce the "no modification" policy as required by Department of the Army.
- (4) During March a VNAF IAM planning conference was held by USARV. ..ir-craft maintenance areas in question were discussed by HQ, USARV-AVN, 34th GSG, and lst Aviation Brigade aircraft maintenance personnel. General guidelines were set forth for all phases of the forthcoming unit conversion. The Brigade All bagin Phase I on 1 June 1970.
- (5) The USARV Pacilities Roview Board approved the following 1st liviation Erigade construction requests during the quarter:

USARY PROJ #	DESCRIPTION	SCOPE
734	Afld Pavement, Vinh Long	39,000 SY
734	Lendfill, Vinh Long	73,000 CM
757	Moct Dist, Can Tho	4,000 LF
757	Lat/Shower, Can T.o	MER
757	Trp Housing, Can Tho	380 tai
757	Mess Hall, Can Tho	6,240 EF
757	Hardstand, Can Tho	107 SY
853	Security Lighting, Mha Trang	14,300 LF
938	Rwy/Parking, Can Tho	65,000 SI
933	Landfill, Can Tho	1.00,000 Cli
993	Acit Fark Apron, Con Tho	42,000 CY
995	BOQ, Can Tho	4,320 OF

AVBAGC-0

SUBJECT: Operational Report-Les one Learned for Headquarters, 1st Aviation
Brigade, Period Ending 30 April 1970, NCS CSFOR-65 (R2) (U)

USARV PROJ #	DESCRIPTION	SCOPE
9 95	EM Billets, Con Tho	10,560 SF
995	Admin/Opn/Sup, Can Tho	2,360 ST
995	Lat/Shover, Con Tho	: E r
995	Water Storage, Con The	· 10 TC
995	Mess Halls, Can Tho	3,840 SF
995	Acft Maint Hangar, Can Tho	2,880 SF
995	Elect Pwr/Dist, Can Tho	100 KV
2167	Acft Dir Fuel, Vinh Long	12 OL
2266	Acft Dir Fuel, Plantation	15 OL

- (6) Portable revetuent closures (4th side) for high dellar himself were designed, tested and approved for construction for all CH-54, CV-1 and YO-3A aircraft in HVN.
- (7) Brazier well requirements and design ariteria for samed helicopters were distributed to all applicable units.
- (6) Dust continues to adversely affect exiction operations. Dust his been a contributing factor in five aircraft additions during this quarter, resulting in the loss of valuable aircraft and personnel. Melicoptic operating errors have been given first priority for use of panagrime.
- (9) The ASP for the 145th CAB was completed at Bian Hoa. Five large modules expable of holding 5000 lbs of explosives each were constructed.
- (10) Construction of revetments, terrivers, hardstend, maintenance cases and other necessary facilities for the move of the 73rd SAC and the 54th UAC from Vung Tau to Long Thanh was completed during this period.
- (11) The officer and unlisted billet project for the 117th AND and the 195th AND at Plantation was started. Construction is being accomplished on a self-help basis.
- (12) The approved plan for construction of parallel autorotation lanes, 60° x 500° each, on the eastern perimeter of the Long Binh Post has been tasked to the 20th Engineer Brigade. These landing lanes will be for the use of the USARV Instructor Pilot School and Transition Training Teams. Construction is to be completed by 1 June 70.
- (13) Work was begun on the YO-32 revetments at Long Thanh NLAF. The operational support construction will be completed in time to accept the new circumst.
 - (14) REPORTS OF SURVEY:
 Number Processed 612
 Personnel Hold Minble 72
 Personnel Relieved From Minbility 540
 Dollar Value: \$6,296,183.98

AVRIGO-0

15 May 1970

SUBJECT: Operational Report-Lessons Learned for Headquarture, lot Aviation

Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (15) There were 237 Combat Losses, DD Form 2408-7, processed and approved.
- (16) Items of excess equipment, valued at \$350,560, were receivered and accountability reastabilished. 30 Brisade Units contributed to this program.
 - (17) There were 57 requests for temporary leans processed.
- (18) (a) The drawloun of US Forces initially resulted in problems unintaining adequate stockage of committee and POL levels at stayoficide in the Delta. These stayoficide reduce rearm and refuel turn around time in support of tactical operations.
 - (b) The shortcomings are being received by:
- 1. Movement by ANVH of amounition from Delta ASPs and POL from Can The/Binh Thuy to forward stagefields.
 - 2. Deliveries by commercial oil commentes.
- 2. Increased temporary and permunent bulk storms especial as at forward stagefields.
 - 4. US Aimy operatod logistical backup.
 - f. 10
- (1) Home Four Hous Releases: During the month of April, 2,170 HTHR's were sent to Krnses City-up from 1,592 for March.
- (2) Mitorial Releases: During April this office sent out 50 editorial releases to relatery and civilian publications, up from 41 for Parch.
- (3) Ibiltiple Serson Slide Presentation: "The World I See," the story of Army Arietion in Victoria, has been propared and sersoned. At the present time, 186 slides are show during the 8 minute presentation. Once the finishing radiations are made, the program will be propared for presentation during the upcoming AMA convention.
- (4) Di Film Project: During the early weeks of April, 4,500 feet of color notion ricture film was duct for the Department of the imp. This special project depicted the use of the armed helicopter and fixed using strike aircraft in a combat invironment. Film teams from the South East Asia Pictorial Center were used for this project.
 - (5) Special Purchases: During the most month, this office ecominated the purchase and delivery of 10,000 Brigade Postcards, 30,000 Combat Cortificates, and 1,000 Brigade Stickers.
 - (6) Unit Day Publicity: The following is planned publicity for Unit Day, 25 How:
 - (a) 25,000 copies of the CC's Unit Day Hessage are being reproduced for distribution to each member of the Brigado.
 - (b) A syscial photo spread and foature story on this subject will be distributed to military and civilian publications.
 - (c) HANK Breazine will corry the CG's nessore.
 - (A) I photo story and script will be forwarded to AFVE radio and TV for sixtur on 25 May.

AVRAGG-O
SUBJECT: Operational Report-Lessons Lemmed for Westquarters, 1st Aviation
Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (32) (U)

(7) The Information Office requisitioned and received a special fund eite for \$770.00 from the USARY Centual Welfare Fund Council for the purchase of 1st Aviation Brigade, Vietnam Combat Cartificates to be awarded to all members of the 1st Aviation Enlande. The certainfecte will attache the duration of assignment and appear over the Commanding General's signsture in the lower right hand corner and the individual's commandation officer's signsture in the lower left hand corner. This serves as a momento and an appreciation of service to the 1st Aviation Emigade.

h. Surgeon

- (1) Personnel. During the reporting period the Brigade had no sustained critical shortages of medical personnel. All 50 flight surgeon positions were filled during most of the veriod. Administrative officers were assigned at the group level during the entire period in addition to the Brigade surgeon's office. However, none of the line is a deministrative officer positions were filled at the Battelion level. The botal enhicted strength remained at almost 100% fill; however the experience level dropped materially.
- (2) Operations. There was a large insucase in disposition instructions for medical natorial received from USARV. It related to a remeasion and extension of empiration dates for medications and destruction information The increase in the requirement for group surgeons to retransmit messages was plecing a time consuming burden upon their administrative staffs. In addition there was a nurked increase in the mobability of serious expens A quality control system was initiated which assured that noe scary information was received by all medical facilities on a timely basic. Rather then retransmitting in message form, the information is typed on stencils and disseminated as technical letters called Quality Contact Documents (QCDs). Each QCD is given a control number and is referred to by that number in all subsequent communications. Control numbers are consecutive and butin thi Ol ode's calendar year (i.e. 1970 is Ol-70, 02-70...; 1971 is Ol-71...). This is important because there are many similar QDs and . it is necessary to be able to identify each specifically. The advantages of the system over retransmitting are:
 - (a) Stoncils are casius to type.
- (b) Aviation groups are no longer propriet to matriment reserves concerning suspension or extension of patency inter or destruction information for moderal material.
- (c) Medical facilities know that if a number in the control number sequence is missing, they need to take action to prover the description is an important facture of the system. This was an explicitly without a material increase in the Brigada surgeon's worklood call resulted in an important cawings in men-hours at the group level.

AVBAGC-0

SUBJECT: Operational Report-Lessons Learned for Handquarters, 1st Aviation

Brigade, Period Ending 50 April 1970, RCS CSPOR-65 (R2) (U)

i. Scfoty.

- (1) The lat Aviation Brigade flow 451,518 hours during the reporting period and experienced 87 aircraft accidents. The direct accident rate for the quarter based on 100,000 flying hours was 19.2.
- (2) 53 percent of the total accidents during this quarter resulted from human cause factors. Engine failures were the greatest material cause factor and accounted for 30% of the total accidents. Tail roter failures increased from the provious quarter with a total of 8 tail roter failure accidents. Loss of EPN accidents increased with a total of 17 accidents.
- (5) Fixed wing accidents accounted for 9 of the 37 accidents representing an upward trend of fixed wing accidents. Pixed wing accidents rate for this quarter was 11-1 compared to the 21-2 rate for ratery wing per 100,000 flying hours.
- (4) During the last quarter the Lyintion Safety Section visited a total of 76 battalion and employ size units. These visits proved boneficial in assisting the eviation accident prevention program down to the lowest level.
 - (5) Aircraft Accident Statistics

<u>нтном</u>	TOTAL FLYING HOURS	NO. ACCIDENTS	P.TE*
Feb	142,113	26	18.3
Mer	156,249	30	19.2
Apr	153,156	31	20.2

^{*} per 100,000 flying hours

- (6) IEC Ronald H. Horritt assumed the duties of Lyinttion Safety Officer during this quarter. He replaced ITC Clement L. Hyllic who was assigned to the 222nd CIB as Commending Officer.
- (7) I test program for flying hours was approved and sent to selected units. The program consists of 35 hours based on a 7 day week. The test is to determine the number of hours an aviator can safely fly, without fatigue. The test period is for 60 days.
- (8) Project Impact was initiated during this quarter to reach both aviation and ground personnel. Use of AFVII radio for spot safety announcements and a continuing series in the Penerum program concerning aviation. Safety has been arranged with the AFVII programming officer.

AVBAGO-O SUBJECT: Operational Report-Jessons Learned for Headquerters, lot Aviation Brigede, Period Ending 30 April 1970, RCS CSFCR-65 (R2) (V)

j. Chaplain.

The following describes Chaplain activities within 1st Iniction Brigade for the period ending 30 April 1970.

(1) Group Roligious Services:

Number conducted - 1546 Number attending -37142

(2) Religious Education

Number of occasions - 678
Number attending -10431

(3) Character Guidence

Number of occasions - 329
Number attending - 44641

- (4) Humber of Postoral Visits 28673
- (5) Tri-Faith Roligious Retreat
- (a) Conducted in 12th Aviation Group (b) Number of "Duty Deys with God" -15
- (c) Humber of people attending -542
- (d) Percentage of unit personnel attending %
- k. Hoodquarters Commandant Home
- 1. Mistorica

=;

- (1) Combat Art Tegn. During the reporting period a two men combat art team was formed and assigned to the Brigade Historical Section. Twelve oil paintings were completed and registered as historical properties.
- (2) Combet lifter Action Interview Reports. L'embet efter action interview report program was initiated for Combet Aviation Bettalions. Five combat efter action interview reports were completed and submitted to the Office of the Chief of Hillitary History.
- (3) Historical Collection. A Brigade Historical Collection was established at Brigade Hordquarters. Hime captured enemy vengens and fifteen items of captured enemy equipment were acquired for the collection.

14

AVRIGG-O.

SUBJECT: Operational Report-Lessons Learned for Headquarters, let Aviation
Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (4) <u>Gapsule Mstory</u>. A capsule history of the 1st Aviation Brigade was written during the reporting period. Arrangements were rule for an initial printing of 15,000 copies to be distributed to visitors and incoming personnel.
- (5) Unit Historics/Amual Historical Supplements. Eighty-one unit historical supplements for 1969 were submitted to the Office of the Chief of Military History.
- (6) End-of-Tour Interviews. Six tape recorded end-of-tour Interviews of Bettalion/Squadron Commanders were conducted and submitted to the Office of the Chief of Military History.
- 2. (C) Section II. Lessons Learned: Communder's Observation, Evaluation, and Recommendations.

c. Personnel

Unauthorized Ran Quotas

- (1) Observation: Eunerous personnel reassigned in Britade receive a second allocation from their new cornend. Second RERs are not authorized during appreciation of the contract of the contra
- (2) Evaluation: The only record of RAR taken is a copy of orders placed in an individual's 201 file. During the transfer, the individual need only destroy the copies in the file and request a new allocation when he reaches his new corrend. These instances jeopardize others from receiving an allocation to which they are entitled.
- (3) Recommendation: That a cortificate be issued by the commander of the losing unit certifying that the individual has or has not used an RAR allocation. The certificate would be maintained in the 201 file and notation and on the Installation Clearance Record, DA Form 137.
- (4) Command Action: This Headquarters is initiating positive controls over the allocation of RAR's to proclude unfair distribution. RAR will be recorded on Form: 20/66 in duty status block.

b. Operations.

- (1) Insufficient OH-58 Pilots.
- (a) Observation: The OH-58 New Equipment Training Term (IEMT) was wantble to train sufficient OH-58 pilots to meet the needs of the Brigado.

AVELOC-0

SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Aviation Brigado, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (b) Evaluations To expend the HETT school would tie up more assets in personnel and aircraft. The availability of facilities to accommodate such an expension at this time was critical. The other alternative was to task subordinate units to develop a unit transition program with the assistance of the Brigade Standardization Section.
- (c) Becommendation: Subordinate units were directed to establish a unit transition program to include the same ground school program of instruction and flight syllabus used by the NETT. Prorequisites for attendance would be the same as required for the METT school.
- (d) Command Action: Under the supervision and staff assistance of the Brigade Standardization Section, subordinate units are now transitioning OH-58 pilots. This course of action has resolved the problem.
 - (2) Dropped Loads.
- (a) Observations The 1st inicition Brigade had experienced an increased number of dropped locals from CH-47 aircraft during this period.
- (b) Evaluation: The loads were dropped or punched off due to faulty sling equipment, carolog rigging and oscillation of the load as a result of excessive airspeed.
 - (c) Recommendations:
- L. All supported units and supporting units will receive additional training in the proper method of rigging and inspecting sling loads and sling equipment.
- 2. Pathfinders are qualified to train personnel in the proper method of rigging loads. They should make assistance visits to supported units and instruct personnel on proper rigging procedures and how to identify faulty equipment.
- 3. When fixed win remft are recovered by CE-47, where practicable, the wings are to be remove arrived internally. If not, insure that spoilers are on the wings and to the control locks are engaged.
- 4. The indicated and of the recovery siremft (IAS) will not exceed the indicated and incremft as a sling load.
- 5. CH-47 crows and Ch. I crows will review and execute procedures cutlined in the appropriate -10 manual.

AVELGC-0

SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Lyiation
Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (d) Command Letion: This Herdquarters has discommated instructions to all subordinate units to implement the recommandations listed in paragraph 2b(2) (c) above.
 - c. Training.

Carlotte Carlotte

- (1) In-Country Training.
- (a) Observation: The in-country training required for LH-1G, OH-6, and OH-58 pilets and instructor pilets requires diversion of mission assential aircraft and highly qualified personnal.
- (b) Evaluation: The training of pilots and instructor pilots for the AH-1G, OH-6 and OH-58 should be increased in CONUS to not the needs of units deployed in NVH. Assets within the Britishe must be diverted from the principalisation in many cases to satisfy a training qualification program.
- (c) Incommendation: That CONUS Schools increase the cutput of pilots and instructor pilots in the AN-IG, OH-6 and OH-58. Instructor pilots should be second tour aviators and should definitely not be turn around pilots who have just graduated from flight school.
- (d) Command Letien: USANV has advised DA of the need for increased output of aviators trained in these aircraft.
 - (2) First Tour Turn Around Instructor Pilots.
- (a) Observation: In unusually high accident/incident rate has resulted during training missions involving instructor pilots who attended Instructor Pilot School immediately after graduating from flight school.
- (b) Evaluation: Recent accidents/incidents involving instructor pilots just out of flight school has amphasized the requirement for more flight experience prior to assuring instructor pilot duties. The instructor with 250 hours total flight time is not able to cope with the problems and emergencies that occur during transition and mission training.
- (c) Recommendation: Each IP or potential IP must have 600 hours of total military time, 200 hours in model and 25 hours in series before assuming IP duties. Experience has established that it is not practical to send new eviators through instructor pilot courses immediately after graduation from flight school.
- (d) Command Action: The recommendations listed in paragraph 2c(2)(c) above have been implemented through directives. Standardization training visits are being made to subordinate units to assist them in qualifying experienced and nature evictors to become instructor pilots.

AVEAGC-0
SUBJECT: Operational Report-Leasons Learned for Readquarters, 1st Eviation
Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (3) First Tour Aviators Knowledge in Capabilities and Limitations of the UK-1 Helicopter.
- (c) Observation: Newly rated evictors are not sufficiently familiar with the capabilities and limitations of the UH-1.
- (b) Evaluation: Evaluation rides and investigations of accidents involving aviators with 25 to 300 hours as a military rated pilot have revealed a lack of knowledge in the capabilities and limitations of the UH-1. The new aviator is unable to compute the load carrying capabilities and does not understand the limitations of the helicopter under varying conditions.
- (c) Recommendations: During flight training special emphasis should be placed on the capabilities and limitations of the UH-1 to include procedures for utilizing the GO-WO-GO placerd and high altitude and density altitude operations.
- (d) Command Action: Each new evictor is given a minimum of 3 hours classroom instruction on the empabilities and limitations of the UH-1 Helicopter before he is released to fly. Ground school is being conducted at unit level to qualify the new evictor to operate under the existing conditions.
- (4) First Tour Arietors Knowledge of Aircraft Systems and Emergency Procedures in the UH- Helicopter.
- (a) Observation: First tour evictors are not familiar with certain aircenft systems and the not result is an imability to cope with energency situations.
- (b) Evaluation: The Brigade standardization program has revealed a lack of knowledge of the fuel, hydraulic and electrical systems.
- -(c) Recommendations: That more time be devoted to training student pilots in the operation of the fuel control in automatic and emergency position, the hydraulic system to include the function of the electrically operated control switch, and the electrical system to include functioning of the inverters.
- (d) Cormand Action: Classes on aircraft systems and emergency procedures are presently being conducted for all new evictors.
 - d. Intelligence NONE.
 - o. Logistics
 - (1) T53 Turbine Engine Maintenance Program.

AVBLGG-0
SUBJECT: Operational Report-Lessons Learned For Headquarters, 1st Lymation
Brigale, Period Ending 30 April 1970, NCS CSFOR-65 (N2) (U)

- (a) Observation: There continued to be an excessive number of turbing engine changes during the past quarter.
- (b) Evaluations: Stoff assistance visits to Brigade units revealed that the T53 engine was being changed and togged as equipment failure due to a lack of parts, tools and/or experienced repair personnel.
- (c) Recommendation: The Brigade Livereft Maintenance Section should propore a procedural guide on steps to be taken in conducting through scheduled inspections and detailed procedures to be followed in repairing T53 engines which is within the authorized cehelon of maintenance at unit level.
- (d) Command Action: The Brigade Maintenance Section in a compiled checklists for both teardour and build-up of engines. This can step by step lists designed to reduce errors in maintenance procedures and to prevent the presenture turn-in of reprincible engines. These lists have been issued to all appropriate units. Additionally, the Brigade Aircraft Maintenance Section began an expressive program of steff maintenance assistance visits to units experiencing maintenance difficulties.
 - (2) UH-ID Liveract for 8th US large:
- (a) Observation: The 1st Aviation Brigade, during the past quarter was required to furnish 42 UH-ID aircraft for transfer to the 8th Army in Korac. This requirement specified that only UH-ID aircraft with less than 1100 airframe hours since now or overhold would be condidates for transfer. The criteria for transfer was never established by higher headquarters until the "trade out" was already in progress.
- (b) Evaluation: Because of the diffrance how cultures not forth, as many as seven element per unit had to be calcated for transfer. It was originally understood that the owning unit would perform all organizational maintenance and the next periodic inspection. However, it was intended that all aircraft components were to be changed IAV the standard of services while ty presented in the current -20 maintenance manual. During the time that was required to resolve these differences and correct the discrepancies, the owning unit had aircraft which were open tionally peady but could not be utilized to perform the units mission.
- (c) Recommendation. In the future all transfer emitaric should be themorphly resolved prior to initiating the properation propers.
 - (a) Command Letion:
 - 1. USIN has requested DA to change the criteria for transfer.

CONFIDENTIAL

AVBAGC-O

15 May 1970

SUBJECT: Operational Report-Lessons Learned for Headquarters, lst Aviation

Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (3) CH-47C, T55-L11 Enginer Problems
- (a) Observations: Many problems were encountered with the T55-L11 engines installed on the CH-47C aircraft. Excessive down time was caused by a separation between the combustor housing and fuel manifold, internal oil leaks and chaffing of the fuel nozzles.
- (b) Evaluation: Lycoming devised a temporary solution for engines in the field and began a study to redesign future engines. The fuel nozzle chaffing is not a serious problem. The internal oil leaks are undergoing study and tests by AVSCOM and Lycoming.
- (c) Recommendations: That specialized personnel be made available to each unit operating the T55-L11 engine so that a more professional evaluation can be made for each problem.
- (d) Command Action: This Headquarters is closely monitoring problems encountered on the CH-47C with special assistance from the AVSCOM project office and senior Lycoming representatives.
 - (4) SPH-4 Helmet Supply
- (a) Observation: Brigade units were turning in helmets to the property disposal officer when the helmet did not meet disposal criteria.
- (b) Evaluation: Helmets that do not have structural damage can be repaired by utilizing electronic kit assembly, FSN 5820-134-3867. When they are turned in to property disposal they are normally burned.
- (c) Recommendation: That adequate repair parts be placed on requisition to repair all unserviceable helmets on hand. That demand data be maintained on repair parts so that PLL stocks will meet the supply demands.
- (d) Command Action: A message was sent to all units of the Brigade directing no helmets be turned in to property disposal unless structurally damaged. Units were also directed to establish PLL's and follow up on outstanding requisitions for helmet repair parts.
 - (5) Movable Revetment Closures.
- (a) Observation: CH-54, OV-1 and YO-3A aircraft are high dollar aircraft and are lucrative targets for morter, rocket and direct small arms fire.

AVRIGO-0

SUBJECT: Operational Report-Lessons Loamed for Headquarters, 1st Aviation

Brigade, Poriod Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (b) Evaluation: Recent nortar attacks on sirfields and heliports caused significant loss of material. Because of the increase in indirect fire attacks, additional protection is required for high dollar sireraft.
- (c) Recommendation: That all CH-54, OV-1 and YO-3A be provided enclosed revetuents.
 - (d) Command Action:
- 1. Entineers were requested to develop a novable revetuant which would found fourth side for the existing three sided revoluents. Mevable revetuents were constructed on warehouse trailers utilizing MBAI matting to make an "A4" from 11.5 feet tall. The design was approved and tosts of the revoluents were constructed at Sanford AAF, Long Binh.
- 2. A mostage has been sent to all units providing this distoric and required has for morable revetment closures. In Levincer operational support to provide the construction of novable executes for all Ca-54 and OV-1 aircraft in RVH. Another request will be submitted for the YO-32 aircraft when firm stationing data becomes available.
 - (6) Slagufield Barrier Walls
- (a) Observation: Many existing stagefields which are fragmently utilized for meaning AM-1G gunships do not have 9.5 ft. barrier wills for protection against mockets insevertently fired from marked gunships.
- (b) Evaluation: Recent accidents involving the accidental firing of 2.75 m rockets have revealed the inadequacy of existing helicopter gunship barrier walls.
- (c) Recommendation: That all frequently used stagefields be provided 7.5 it. barrier walls at rearring points for AH-16 gunships. Earrier walls may be constructed by utilizing earth filled drums and MOAI matting.
- (d) Command Action: A message has been sont to all units to unguade existing revetuent barriers at frequently used stoposicida to 9.5 ft.
 - (7) Electrical Wiring Huzards.
- (a) Observation: Recent inspections of units billets have revealed that faulty and potentially dangerous electrical wiring conditions exist.

AVBAGC-0
SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Aviation
Brigade, Period Ending 30 April 1970, RGS CSFOR-65 (R2) (U)

- (b) Evaluation: Self-help construction projects and modification of existing billets by unit personnel not qualified to perform electrical wiring tasks have resulted in many billets having faulty electrical wiring. These billets and work areas are potential fire hazards to all personnel and material housed within such structures.
- (c) Recommendation: That commanders at every level take necessary action to eliminate such conditions and establish controls to prevent recurrence.
- (d) Command Action: A message has been sent to all units depicting common electrical wiring hazards and emphasizing the need for continued command interest in detecting and eliminating these hazards. Additionally, commanders will insure that only qualified personnel are permitted to install, repair or modify electrical wiring.
 - f. Organization NONE.
 - g. Information NONE.
 - h. Signal
 - (1) Identification of Avionics Training/Experience MOS 266A
- (a) Observation: There is no method which identifies Avionics training or experience in MOS 286A.
 - (b) Evaluation:
- 1. MOS 286A is assigned to supervise and manage avionics direct support maintenance shops in aviation companies. The MOS description does not require a knowledge of avionics or aircraft electronics systems. In fact some of the enlisted feeder MOS's from which appointments to MOS 286A may be made have very little electronics background. As a result experience has shown that a two to four months learning period is required for the Warrant Officer, MOS 286A, who has had no previous avionics/electronics experience. As new aircraft enter the system with more avionics systems and subsystems, it becomes more important than ever that the maintenance shops have experienced or trained supervisors.
- 2. Personnel who gain avionics experience should be identified easily for assignment/reassignment purposes. Presently they are identified only by personal knowledge or the job title reflected on the officer qualification record. Consequently all MOS 286A appear to be the same once they have entered into the replacement stream, and the expertise is frequently lost.

. V BAGC-O

15 May 1970

SUBJLICT:

Orerational Report-Lessons Learned for Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970, ECS CSFCR-65 (E2) (U)

- (c) Recommendation: That an Additional Skill Identifier be assigned to identify those Warrent Officer technicians who have training or experience in avionics or aircraft electronics.
- (d) Command Action: The Brigade will sub it a recommendation that paragraph 2h(1)(c) above be implemented.
 - (2) Ineffective DS Avionics Maintenance at Unit Lovel.
- (a) Observation: Assault and assault sumport hal coptor companies do not effectively use the organic DS aviences maintenance capability.
 - (b) Evaluation:
- 1. Helicopter companies have an organic capability to perform organizational and DS maintenance on avionics equipment. Numerous companies are not exploiting this capability for several reasons: 1) Lack of sufficient supervisors; 2) Lack of sufficient test equipment or excessive down-time for repair of test equipment; 3) Lack of trained personnel in authorized MOS's,
- 2. A shortage of selected, but required, avionics test equipment exists. Frequency generators and frequency counters were not available in sufficient quantities to meet demands. Some units have had items on request in excess of six months. Still others experience excessive delays in getting test equipment repaired and calibrated.
- 3. Supervisory personnel MOS 286A and 35P40 are critically short. The Brigade is authorized 76 MOS 35P40 but had only 51 assigned; 44 MOS 286A are authorized and only 36 are assigned.
- 4. Avionics MOS personnel are in short supply. Overage MOS's in related fields are being cross trained as rapidly as possible, but this has provided only temporary and partial relief.

AVBAGC-0

SUBJECT: Operational Report - Lessons Learned for Headquarter, 1st Aviation Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (c) Recommendation: That one avionics repair facility be used, derived by combining two or more unit facilities located at the same airfield or installation and supervised by the Signal Officer of a battalion or other senior headquarters. This tends to overcome the shortages of both test equipment and personnel and improve overall effectiveness and efficiency. Conversely, it affects the capability of rapid movement of a company with its full organic capability.
- (d) Command Action: Some units have initiated consolidated avionics facilities at relatively fixed bases where the units mission is such that the units are not likely to move. Sufficient unit integrity of avionics repair must be maintained in the event the unit is deployed on short notice. The Brigade Signal Staff is evaluating the airfields where combining of avionics facilities appears to be advantageous.
 - (3) Excess DS Avionics Maintenance Facilities
- (a) Observation: There is much duplication of DS avionics repair facilities, amplified by concurrent stationing of aviation units at an airfield.
- (b) Evaluation: The 1st Aviation Brigade has 74 DS avionics repair facilities, organic or attached to company/troop-size units. All are located at an airfield or heliport with at least one other DS avionics maintenance facility, except for three units. In one case there are seven DS facilities and one back-up DS/GS facility at one air field; in another similar case there are five DS facilities and a back-up DS/GS facility. This does not include the capability provided each airfield detachment.
- 1. Some facilities have been combined to cause more effective and efficient operations. But such combining still requires separate PLL's, document registers, etc, to be maintained while the back-up DS/GS facility still exists with noticeable duplication.
- 2. A single DS/GS facility consisting of 30-50 personnel at each airfield could provide effective, efficient support to all tenant units at that airfield as well as any transient requirements. With slight tailoring it could handle a single company or up to 10 companies. This would result in great savings of personnel and equipment. Rough estimates indicate a potential savings of nearly fifty percent of present in-country assets.
- (c) Recommendation: Study the possibility of utilizing a single DS/GS avionics maintenance facility at each mirfield with a corollary reduction in the DS capability at unit level.

AV BAGC-O

15 May 1970

SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (d) Command Action: This Headquarters is currently evaluating the advantages of consolidated avionics maintenance facilities.
 - 1. Surgeon

Chest Protector Armor (CPA)

- (a) Observation: From July through October 1969, a number of individuals were admitted to hospitals in RVN with severe lacerations caused by chect protector armor striking the chin when an aircraft was downed. Some of these wounded had fractured lower jaws which, in a few instances, were considered severe injuries.
- (b) Evaluation: The following comments are based on a survey which requested information on injuries to personnel who continely wore armor. In summarizing the results of this survey, the total injury rate, excluding a unit experiencing an abnormally high accident rate, was 6.28 injuries per 1,000 men per annum. For severe lacerations, the rate of injury was 1.05 per 1,000 men per annum and the rate at which bruises occurred was 2.62/1,000/annum. In comparison to these average rates, the unit experiencing the high rates, experienced injury rates 20 times the average rate. This difference is explained largely by improper size, improper wear, and wearing armor on all missions, not just on combat missions.
 - (c) Recommendations:
 - 1. All personnel wear armor during airborne combat assaults.
- Insofar as possible, personnel should wear the proper size armor.Armor should be issued to individuals.
- 3. Armor should be snugly fastened and worn under the harness. Plates should not be worn without the carrier vest.
- (d) Command Action: All units are being reminded to insure that all crew members have properly fitted armor and that it is correctly worn on all combat operations.
 - j. Safety
 - (1) Aviation Safety Officers
- (a) Observation: A shortage of aviation safety officers exists within the Brigade.

AVRICC-0
SUBJECT: Operational Report-Leasons Learned for Headquarters, 1st Lviation
Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (N2) (U)

(b) Evaluation: There are a total of 104 authorized positions for school trained eviation safety officers within the Brigade. A total of 58 school trained safety officers are currently assigned within the Brigade with 23 of the 58 filling aviation safety officer positions. The remainder are being utilized within the various command chains.

(c) Recommendations:

- 1. That an in-country school be established to train these officers filling aviation safety officer positions who are not graduates of the USC Safety Course.
- 2. That the lat Aviation Brigade carefully control the placement of aviation safety officers within the Brigade to insure full utilization of the limited number.
- 3. That the output quote at USC be increased to provide the number of school trained aviation safety efficient needed.

(d) Corrand Action:

- 1. Contact was made with USAABAR and USARV to establish a valid requirement for the school. USAABAR responded favorably and classes are scheduled for 6 May through 3 June 1970. 165 quotes were allocated to the Brigade.
- 2. The lat Aviation Brigade Safety Office interviews all aviation safety officers scheduled for among or battalion safety position prior to assignment.
- 3. Command action was initiated by a briefing to Lieutenant General Walter T. Kerwin Jr., DCSPIR, and Major General William A. Mannark, Inspector General, Department of the Army, regarding the critical shortages of existion safety officers.

(2) Airfield Safety Councils

- (a) Observation: A lack of coordination between tenant units at airfields utilized by the lst Aviation Brigade has created a safety problem.
- (b) Evaluation: Some of the smaller airfields which have both rotary wing and fixed wing aircraft parked in the same general area were lacking procedures and coordination to insure safe operation of aircraft at all times.
- (c) Recommendation: Airfield Safety Councils should be established at Brigade used airfields. These safety councils should include representatives of all units concerned and review all aspects of airfield safety.

AVMAGC-0

15 May 1970

SUBJECT: Operational Report-Lessons Louned for Headquerters, 1st Aviation Brigade, Poriod Ending 50 April 1970, RCS CSPOR-65 (N2) (U)

- (d) Action: Airfield cafety councils were estab ished by direction of the Drigade Commander.
 - (3) Inadvertent Rocket Firings
- (a) Observation: A series of incovertent firings of the 2.75% rocket continued to use a perious problem within the Brigade.
- (b) Evaluation: The inadvertent rocket firings were nostly the result of ground crows failing to follow the established procedures and to newform the localing/valuading operations in authorized areas.
- (c) Recommendation: That communders appoint an aviator is the armament officer. He would insure that loading and unloading of armed aircraft is accomplished proporty and in an authorized area.
 - (d) Comand Action:
- L. Hajor Mandelsohn, Armanent Division, 34th Croup make many presentations to Brigade personnel on loading and unloading procedures. He also made a seriou of audio tapes for distribution to subordinate units which could not attend his presentations.
- 2. Several field attempth indicator kits, for testing stray voltage and radio emissions, are being made for distribution to the units.
- 3. Subject was addressed in monthly safety report and the HAVE Gram. In christian, I messages were sent to subordinate units.
 - k. Staff Judge Mivocate.
 - (1) Pro-Tricl Confinement
- (a) Observation: Individuals held in pre-trial confinement are not being tried within 15 days of the date on which they were confined, as required by USLIV respulation.
- (b) Evaluation: In most cases, the delay in trial is due to difficulty in obtaining a military judge or as the result of requests for below by defense counsel.
- (c) Recommendation: That pre-trial confinement be closely monitored to insure that proper justification exists in easier of excessive periods of pro-trial confinement.

AVBAGC-0 15 May 1970 SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st initiation Brigado, Pariod Ending 30 .pril 1970, RCS CSFOR-65 (R2) (U)

- (d) Command Action: The Staff Judge Advocate of this headquarters closely monitors pre-trial confinement to insure compliance with the appropriate regulations.
 - (2) Search and Seizure
- (a) Observation: Many commanders do not understand the probable cause requirement for the authorization of searches and seizures.
- (b) Evaluation: Commanders are not well-informed as to what kind of facts must be known to them before they can authorize a valid search. Confusion also erists concerning the admissibility in court of items seized in a "shakedown inspection.
- (c) Recommendation: That loctures on the law of scarch and scizure be given at the monthly Newly Assigned Commanders Conference.
- (d) Command Action: This headquarters now promote loctures on laws of search and soigure at the Nowly Assigned Commandors Confurence.
 - (3) Military disciplino
- (a) Observation: The Erigade Headquarters must monitor military justice activities throughout the Brigade.
- (b) Evaluation: The monthly reporting of military justice activities by subordinato Hoadquartors is essential if the Commanding General is to be aware of the status of military discipline throughout the Brigade. Subordinato Headquarters should also notify the Brigade of any pending Article 32 Investigations in order that the Commanding General be aware of trends and disciplinary problems.
- (c) Recommendation: That Group Headquarters submit monthly reports on military justice activities to include both Article 15 and court martial statistics, that Summary and Special Courts-Martial Convoning Authorities submit copies of all court martial promulgating orders to Brigade Headquarters, and that the Brigade Judge Advocate be advised whenever an Article 32 Investigating Officer is appointed.
- (d) Command Action: This Headquarters now requires subordinate Headquarters to submit information listed in paragraph 2k(b)'s) above.

2 Incl

GEORGE V. PUTNAM, JR. C., Brigadier Gonorel, USA Commanding

DISTRIBUTION:

l cy-Thru channels to ACSFOR (Orig cy)

2 cy-Direct ACSFOR DA (with 1st Ind)

2 cy- Cinusarpac, attn: GPOP-DT 3 cy-cg usarv, attn: avecc-dst

CONFIDENTIAL

Tay-G7 File

AVHCC-DST (15 May 70) 1st Ind

SUBJECT: Operational Report-Lessons Learned for Headquarters, ist Aviation Brigade, Period Ending 30 April 1970, RCS CSFOR-65 (R2)(U)

Headquarters, United States Army Vietnam, APO San Francisco 96375

TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, . . APO 96558

Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

- 1. (U) This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1970 from Headquarters, 1st Aviation Brigade.
- 2. (C) Comments follow:
- a. (U) Reference item concerning "Unauthorized R&R Quotas", page 15, paragraph a(1): nonconcur. The recommendation is not feasible due to the fact that the individual would still be able to destroy the certificate in the 201 file. MACV and USARV endorse the policy of stamping immunization cartificates with the statement "R&R" and the date. Unit has been so advised.
- b. (U) Reference item concerning "Dropped Loads", page 16, paragraph 2b(2): "concur. Command emphasis has been placed on this subject by the Deputy Commanding General, USARV, in his May 1970 Commander's Notes.
- c. (U) Reference item concerning "T53 Turbine Engine Maintenance", page 18, paragraph 2e(1): concur. The need to minimize the number of turbine engine changes increases in importance in light of the present Avco-Lyconing labor strike. USARV Aviation has informed commanders to conserve stocks of serviceable engines and critical repair components.
- d. (C) Reference item concerning "UH-1D Aircraft for Eighth U.S. Army", page 19, paragraph 2e(2): concur. USARV Aviation has requested that USARPAC declare a less stringent airframe hour criterion for those aircraft being transferred to Eighth U.S. Army. Approval of the request would afford USARV greater flexibility in selecting UH-1D aircraft for this intra-theater transfer.
- e. (U) Reference item concerning "CH-47C, T55-Lii Engine Problems", page 20, paragraph 2e(3): concur. USARV Aviation has requested Avco-Iyconing to provide five technical representatives at no expense to this command to assist in the resolution of problems associated with the T55-Lii. USARV has been informed that the five technical representatives will arrive 1 June 1970 for a ninety-day period.

AVHGC-DST (15 May 70) 1st Ind SUBJECT: Operational Report-Lessons Learned for Headquarters, 1st Aviation Brigade, Period Ending 30 April 1970, RCS CSFCR-65 (R2)(U)

- f. (U) Reference item concerning "Moveable Revetment Closures", page 20, paragraph e5: concur. USAECV Drawing DO245 which employs welding and USAECV Drawing DO245A which uses bolts in place of welding are available. The unit cost of these revetments is about \$750.00. Three each of these revetments are required to form a CH-54 door and four or five for an OV-1 door. No action by USARPAC or DA recommended.
- g. (U) Reference item concerning "Electrical Wiring Hazards", page 21, paragraph e(7): concur. USARV Regulation 4.5-1, that is currently being rewritten, will prohibit electrical wiring by self help. Unit has been so addised.
- h. (U) Reference item concerning "Identinication of Avionics Training/Experience, MOS 286A", page 22, paragraph 2h(1): concur. Valuable experience and knowledge is lost as a result of inadequate identification of avionics-trained/experienced personnel having hOS 286A. Action by DA is recommended.
- i. (U) Reference item concerning "DS Avionics Maintenance", pages 24-25, paragraphs 2h(2)(c) thru 2h(3)(d): concur. The consolidation of avionics repair facilities at airfield level would markedly improve support of co-located aviation units. However, contact teams, having test equipment and maintenance float equipment, should be predesignated and available for rapid deployment with deploying aviation units.
- j. (U) Reference item concerning "Aviation Safety Officers", page 25, paragraph j(1): concur. The proposed school has been established. Concerning the recommendation that quotas at the USC Safety School be increased to provide the required number of aviation safety officers: concur. USARV has coordinated an increase in quotas for FY 71. DA has agreed to increase the safety school output sufficiently to provide USARV's authorized number of aviation safety officers during FY 71.
- k. (U) Reference item concerning "Pre-Trial Confinement", page 27, paragraph k(1): concur with the action taken. In addition, this head-quarters has instituted a monitoring system to insure that pre-Trial confinement rerains at a minimum. Little further improvement is likely without an increase in the number of military judges assigned within the command. Six additional full-time military judges certified for special courts-martial would alleviate the problem. Action by DA is recommended.

FOR THE COMMANDER:

1

ASS. L. I Hope

Cy furn: 1st Avn Bde

GPOP-DT (15 May 70) 2d Ind (C)
SUBJECT: Operational Report of HQ, 1st Aviation Brigade, for
Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

HQ, US Army, Pacific, APO San Francisco 96558 $_{2\,\mathrm{b}}$ AUG 70


TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310

- 1. (U)This headquarters concurs in subject report as indorsed except as indicated in comments below.
- 2.(U)Reference paragraph 1d(2), page 4: Copies of subject MTOE will be furnished USARV.
- 3.(C)Reference paragraph 2e(2), page 19: Item states that transfer criteria of 1100 airframe hours or less was not established by higher headquarters until the "trade out" was in progress. The 1100-hour UH-1D transfer criteria for aircraft going to USAEIGHT was established at the February 1970 Aviation Closed Loop Support Conference after lengthy discussions among representatives from USARPAC, USARV, USAEIGHT, and DA. This criteria is also shown on page 1C-1 (UH-1/AH-1G) of the current CLS manual. Based on USARV request and with concurrence of USAEIGHT, USARPAC has changed the criteria for transfer from 1100 to 1300 airframe hours. Authority for the increase is USARPAC Confidential message GPLO-SD-E, DTG 280314Z May 70, subject: UH-1D Aircraft Transfer to USAEIGHT (U).

FOR THE COMMANDER IN CHIEF:

L.M. OZAKI CPT, AGC Asst AG Co USARV

States Comment



ज़ इ

UNCLASSIFIED

182 AVIATION BRIGADE AND ATTACK EXTS

182 4	Wiktion brigade and attachemes	
AVBACC		1 May 1970
Three	244477	150
UHIT	LOCATION	APO
	•	
1ST AVIATION BRIGADE	Long Birth	9638 4
HQ & HQ Co	Long Hinh	96384
<u> </u>	Long Binh	06 20 4
JM 2011 200		70 701.
STA PAI HIST DET	Long Einh	95304
12th Pub Info Det (T)	IFB) Long Binh	96384
•		
478th How Hel Co (-) De	Nong (Atch 101st Alm Div AUCL)	96383
2024 MO Dot (TO) Do	a Heng (Atch 101st Abn Div AICL) a Hang (Atch 101st Abn Div AICL)	96383
yoza To Det (JE) De	r usus (vicu inter vou his wert)	70,707
165th COMBIT IVN CP	Long Binh	96584
HQ & HQ Co	Long Binh	96304
129th Med Det (O.)	Town Dink	06204
	Long Binh (Sanford) Ten Son Mut H-3 (Atch 34th Gen Spt Sp)	0/704
312th Avn Det (Div)	Long Binh (Sanford)	96 384
313th Lvn Det (Div)	Tan Son Mut H-3 (Atch 34th Gen Spt Sp)	9630 9
314th Lvn Det (Div)	Lei Khe (itch 12th CLE)	96289
315th Lvn Det (Div)	Bear Cat (Atch 12th CAG)	96350
	The man and the state of the section	
316th Avn Det (Div)	Long Binh (Plantation) (atch 12th CaG)	96266
317th Avn Det (Div)	Di in (Atch 12th CiG)	96345
318th Avn Det (Div)	An Son (Lane) (Atch 17th ClG)	96 2 26
319th Avn Det (Div)	Bien Hoa (Atch 125th ATC)	96364
320th Lvn Det (Div)	Dunne West (Litab MACV This #2)	96260
201 at the Bot (Blank	Long Binh (Plantation) (atch 12th CLG) Di An (Atch 12th CLG) An Son (Lane) (Atch 17th CLG) Bien Hoa (Atch 125th ATC) Quang Ngai (Atch MACV TH #2) Quang Tri (1/5 Mech Div) Quan Loi (atch 1st Cav Div) Kuan Loc (Atch MACV TH #67) Bien Hoa (Spartan) (Atch 12th CAG) Hue/Phu Bai (101st Abn Div) Dalat (Atch 1st Log Chā) Duc Pho (Atch Americal Div) Vung Tau (Atch 34th GS Gp) Dong Ea Thin (Atch 17th CLG) Fhu Loi (Atch 23rd Arty Gp) Cu Chi (Atch 25th Inf Div)	06 477
521st ivn Det (Div)	drung and (1/2 Necu DIA)	90411
322d Avn Det (Div)	Quan Loi (atch 1st Cav Div)	90490
323d Avn Det (Div)	Xuan Loc (Atch MiCV TM #67)	96376
324th Avn Det (Div)	Bien Hoa (Spartan) (Atch 12th CAG)	96227
• 325th Avn Det (Div)	Hue/Phu Bai (101st Abn Div)	96308
526th Avn Det (Div)	Delet (Ateh lat Log Omi)	96204
ZOZE See Det The	The The (the bearing thin)	06217
327th Avn Det (Div)	Duc Pilo (Atch Merical Div)	20021
338th Lvn Det (Div)	vung Tau (Atch 34th GS Gp)	90291
339th Avn Det (Div)	Dong Ba Thin (Atch 17th CLG)	96577
340th ivn Det (Div)	Phu Loi (Atch 23rd Arty Gp)	96239
341st Avn Det (Div)	Cu Chi (Atch 25th Inf Div)	96353
342d Lvn Det (Div)	Phy Titen (Atab 17th Cic)	96316
2.424 : Det (Dis	And Then (this 3et Inn One)	06228
343d wn Det (Div)	the man (Atch 1st log can)	90270
344th Avn Det (Div)	Plieizu (Atch 17th CLG)	90494
345th wn Det (Div)	Can Tho (atch 164th CAG)	96215
346th Lvn Dot (Div)	Vinh Long (Atch 164th CAG)	96357
347th Lvn Det (Div)	Soe Trens (Atch 164th Cag)	96296
348th Livn Det (Div)	Bon No Phiot (City) (Itch 17th CCC)	96297
SEUTH THE BOT MAN	Come Brown (Stab 101 at the Title)	00.523
359th Avn Det (Div)	Camp syans (Aton Total You 717)	30303 ACAA
360th Lvn Det (Div)	menser (Ytou yu Kije TEC)	90294
361st ivn Det (Div)	Tan in (Atch 9th Inf Div)	95372
362d Avn Det (Div)	Tay Hinh (Atch 25th Inf Div)	962 16
363d Avn Det (Div)	Dong Ea Thin (Atch 17th CAG) Flu Loi (Atch 23rd Arty Gp) Cu Chi (Atch 25th Inf Div) Flu Hiep (Atch 17th CAG) Qui Nhon (Atch 1st Log Crd) Flielru (Atch 16th CAG) Con Tho (Atch 164th CAG) Vinh Long (Atch 164th CAG) Soe Treng (Atch 164th CAG) Ben Me Thuot (City) (Atch 17th CAG) Cemp Byans (Atch 10lst Abn Div) Hensel (Atch 4th CAG) Tan An (Atch 9th Inf Div) Tay Winh (Atch 25th Inf Div) Phan Thiet (Atch 17th CAG)	95317
707- Mil. 400 (MA)	Anna and forest of or Amen	/-/-!

INC/ 2

33

<u>uur</u>	LOCATION	APO
364th Avn Spt Det 365th Avn Spt Det 366th Avn Spt Det	Long Thanh (North) (.tch 12th C.G)	96250 96350 96490
An Khe Airfield Cad	An Khe (Atch 4th Inf Div)	96494
120th Aslt Hel Co	Long Binh	96384
125th Avn Co (ATC)	Bien Hoa	96227
Cmd Aircraft Co	Long Thanh	96350
12TH COMBAT AVN GP HQ & HQ Co 87th QM Det (PETRL) 390th Qf Dot (PETRL)		96266 9626 6 96257 96314
11TH COMBAT AVN BN	Phu Loi Phu Loi	96289 96289
128th Aslt Hel Co 432rd Ned Det (CA)	Phu Loi Phu Loi	96289 96289
173d Aslt Hel Co 759th Med Det	Lai Kho Lai Kho	96289 96289
205th Aslt Spt Hel Co	Phu Loi	9628 9
213th Aslt Spt Hel Co	Phu Loi	962 ଶ9
145TH COMB.T .VV B' HC & HO Co 145th Sec Plt 391st QM Det (FETRL)	Bien Hoa Bien Hoa Bien Hoa Xuan Loc	96227 96227 96227 96376
68th Aslt Hel Co 430th Hed Det (OA)	Bien Hoa Bien Hoo	96227 96227
118th Aslt Hel Co	Bien Hoa	96227
190th Aslt Hel Co 520th Med Det (OA)	Bien Hoa Bion Roa	96227 96227
334th Aeria' Wpns Co	Bien Hoa	96227
210TH COMB/T AVN EN HQ C HQ Co 197th Med Dot (O.)	Long Thanh Long Thanh Long Thanh	96350 96350 96350

<u>W17</u>	LOCATION	APO
25th Avn Co (Corps)	Long Binh (Plantation)	9626 6
54th Util Apl Co	long Thanh	96530
	•	• -
74th Recon Apl Co	Phu Loi	96289
184th Rocon Apl Co	Phu Loi	96289
2270 COMBAT AVN BN RQ & RQ CO	Bear Cat Bear Cat	96350 96350
117th Milt Hel Co	Long Binh(Tlantation)	96384
195th Asia Hel Co 93d Med Det (OA)	Long Binh (Plantation) Long Binh (Plantation)	963 <i>8</i> 4
240th Aslt Hel Co 772d Med Det (QA)	Bear Cat Bear Cat	96 ,350 96 ,350
273d Hvy Hel Co	Long Binh	9 6384
269TH COMBAT AVN BN HQ & HQ Co	Cu Chi Cu Chi	96353 96353
116th Lalt Hel Co 431st Hed Det (OL)	Cu Chi Cu Chi	96 353 9 6353
187th Asit Hel Co 541st Wed Dot (OA)	Tay Ninh Tay Ninh	96216 96216
242d Amlt Spt Hel Co	Cu Chi	96353
3D SQUADRON 17TH AIR CAVALRY HQ & HQ Co A Troop 575th TC Dot (KD) 812th SC Dot (RL)	Di An Di An Di An Di An Di An	96289 96289 96289 96289 96289
B Troop 576th TC Det (KD) 819th SC Det (RL)	Di An Di An Di An	96289 96289 96289
C Troop 369th TC Det (KD) 816th SC Det (KL)	Di An Di An Di An	%269 %269 %269

WIT	LOCATION	NO O
D Troop	Di An	9628 9
16TH COMBIT AVN GE	Chu Lai (Atch 23d Americal Div)	96325
H6 € HC Co	Chu Lai (itch 23d imr Div)	9 6325
14TH COMBIT IN BY 14th Sety Flat 534th Med Det (0%)	Chu Lai (Atch 23d Amer Div) Chu Lai (Atch 23d Amer Div) Chu Lai (Atch 23d Amer Div)	9632° 96325 96325
71st Asit Hol Co	Chu Lai (Atch 23d Amer Div)	96325
132d islt Spt Hel Co	Chu Lai (.tch 23d .mer Div)	96325
174th Aslt Hel Co 756th Med Det (OA)	Due Pho (Atch 23d Amer Div) Due Pho (Atch 23d Amer Div)	96217 96217
176th Aslt Hol Co	Chu Lai (Atch 23d Amer Div)	96325
178th Aslt Spt Hel Co	Chu Lai (Atch 23d Amer Div)	96325
21.2TH COVBLT LIVE EN HC & HC Co 59th SC Det (RL)	Marble Mountain Marble Mountain Hue Phu Bai	96349 96349 96308
21st Recon Apl Co	Chu Lai	96374
131st Surv Apl Co	Huc Phu Bai	96308
220th Recon Apl Co 134th Mcd Det (OA)	Hue Phu Bai Hue Phu Bai	96300 96308
245th Surv ipl Co	Marble Hountain	9 6349
282d Aslt Hel Co 519th Med Det (OA)	Marble Mountain Marble Mountain	96349 96349
62d Corps Avn Co	Marble Mountain	96349
17TH COMB.T .VW GF HQ & HQ Co 25th Med Det	Nhe Trang Nhe Trang Nha Trang	96240 96240
201st Corps Avn Co 58th Avn Det	Nha Trang Nha Trang	96240 96240
10TH COMBIT AVE BN HQ & HQ Co 130th Mcc Det (Q.)	Dong Ba Thin Dong Ba Thin Dong Ba Thin	98377 96377 96377

UNIT	LOCATION	<u>apo</u>
48th Aslt Hel Co 286th Mod Pet (OA)	Minh Hoa Minh Hoa	3657 0 3657 0
92d Aslt Hel Co	Dong Ba Thin	96377
155th Aslt Hel Co Sth Med Det (OA)	Ban Ke Thuot Ban Ke Thuot	96297 96297
192d Aslt Hel Co 198th Med Det (Q.)	Fhan Thiet Phan Thiet	96317 96317
243d Aslt Spt Hel Co	Dong Ba Thin	96377
281st Aslt Hol Co	Nha Trang	96240
52D COMBAT AVE BN HQ & HQ Co 52d Scty Plat 68th Inf Det (RADAR) 94th Med Det (Q)	Pleiku (Camp Holloway) Fleiku (Camp Holloway) Pleiku (Camp Holloway) Fleiku (Camp Holloway) Pleiku (Camp Holloway)	36131 36131 36131 36131
57th Aslt Hel Co	An Khe (Camp Redcliff)	96490
193d Med Dot (OA)	an Khe (Camp Radcliff)	96490
119th Aslt Hel Co	An Khe (Camp Radcliff)	96490
170th Lalt Hel Co 154th Med Det (QL)	Kontum Kontum	96499 96499
179th Aslt Spt Hel Co 755th Med Det (Ck)	Pleiku (Camp Holloway) Fleiku (Camp Holloway)	96494 96494
189th Aslt Hel Co	Pleiku (Camp Holloway)	96494
361st Merial Wors Co 665th TC Det (KD) 621st SC Det (RL)	Pleiku (Camp Holloway) Pleiku (Camp Holloway) Pleiku (Camp Holloway)	96737 96737 96737
223D COMBAT AVN EN HQ & HQ Co 163d Med Det (OA)	Qui Nhon Qui Mhon Qui Nhon	96238 96238 96238
lath Util Apl Co	Qui Nhon	96238
183d Recon Apl Co	Dong Ba Thin	96377
185th Recon Apl Co	Ban Me Thuot	96297
203d Recon Apl Co	Phu Hiep	96316

UNIT	LOCATION	AFO
219th Recon Apl Co	Fleiks (Camp Holloway)	367.37
225th Surv Apl Co	Phu Hiep	96 316
26TH COMBAT AVN EN	Phu Hiep Phu Hiep	9631.4 9631.6
HQ & HQ Co 433d Med Det (OA)	Phu Hiep	96316
61st Aslt Hel Co	An Son (Lame AHT)	9622 6
129th Aslt Hel Co	An Son	96238
134th Aslt H.1 Co	Phu Hiep	96316
180th Aslt Spt Hol Co	Phu Hier	9631 6
196th Aslt Spt Hel Co	An Son	96226
546th Med Det (OA)	in Son	9 6226
355th Hwy Hel Co	Phu Hier	96316
eddi i taalah Mamand Co	Phu Hiep	96316
238th Aerial Weapons Co 587th TC Det (KD)	Phu Hiep	96316
CONTRACTOR ATTOCATION	Pleiku (Camp Holloway)	964.94
7TH SQDN 17TH AIR CAVALE! HQ & HQ Troop	Fleiku (Camp Holloway)	96494
1 Marson	Pleiku (Camp Holloway)	36434
A Troop 288th SC Det (RL)	Pleiku (Camp Holloway)	96494
568th TC Det (KD)	Pleiku (Camp Holloway)	96494
B Troop	Pleiku (Camp Holloway)	96494
414th SC Det (RL)	Pleiku (Camp Holloway)	96494
569th TC Det (KD)	Pleiku (Camp Holloway)	96494
C Thomas	An Khe (Camp Radeliff)	96490
C Troop 238th SC Det (RL)	An Khe (Camp Radcliff)	96490
412th TC Det (KD)	An Khe (Camp Radeliff)	964,90
D Troop	Pleiku (Camp Holloway)	964.94
16LTH COMBLE LAN GP	Can Tho	96215
HQ & HQ CO	Can Tho	96215
52d Cl: Det (PETRL)	Can Tho	96215
Bary H (Search Lt) 29th Arty	Can Tho	96215
62d OM Det (FETRL)	Can Tho	96215
5th QM Det (PETRL)	Can Tho	96215 96215
53d OM Det (PETRL)	Can Tho	96215
267th FA Det	Tinh Binh	702.47

UNIT	LOCATION	041
1945 Seton Blat	Can Tho	96215
13th Scty Plat 78th P.i. Det (RADAR)	Can Tho	96215
268th PA Det	Vinn Gia	96215
261st FA Det (R:D:R)	Vinh Long	96357
269th FA Det	Nui Hon Soc	96215
AH-IG NETT	Vung Tau	96291
CH-6A NETT	Vung Tan	96291
69th Inf Det (RIDAR)	Soc Trang	96296
262d FA Det (RADAR)	Soc Trang	96296
ECEC IN DOU (MEMON)		•
13TH COMBAT AVN BN	Soc Trang	96296
HQ & HQ Co	Soc Trang	96296
41st Mod Det	Soc Trang	96296
121st Lalt Hel Co	Soc Trang	96 296
162d Aslt Hel Co	Can Tho	96215
191st Aslt Hel Co	Can Tho	9 6215
221st Recon Apl Co	. Can Tho	96215
336th Aslt Hel Co	Soc Trang	96296
C TROOP LETH CAV	Soc Trang	363 34
214TH COMEST AVN BN	Vinh Long	96357
HQ & HQ Co	Vinh Long Vinh Long	96357
758th Med Det (QA)	ATIM PortR	
114th islt Hel Co	Vinh Long	96357
135th Aslt Hel Co	Bear Cat	96370
175th islt Hol Co	Vinh Long	% 357
199th Recon Apl Co	Vinh Long	96357
335th Aslt Hel Co	Bear Cat	96370
307M COMBAT AVI EN	Can Tho	96215
HQ & HQ Co	Can Tho	96215
774th Med Det	Can Tho	96215
147th Aslt Spt Hel Co	Vurg Tau	96291
85th Med Det (OA)	Vung Tau	96291
235th Aerial Wors Co	Can Tho	96215
244th Surv Apln Co	Can Tho	96215
73d Surv Apln Co	Long Thanh	96350
12	mand summer.	,-,,,

<u>war</u>	LOCATION	APO
271st Aslt Spt Hel Co	Can Tho	96215
7th SODN 1ST AIR CAVALRY HQ & HQ Troop 83d Med Det (QA)	Vinh Long Vinh Long Vinh Long	96357 96357 96357
A Troop 370th TC Det (KD) 819th SC Det (RL)	Vinh Long Vinh Long Vinh Long	96357 96357 96357
B Troop 57%th TC Det (KD) Slith SC Det (RL)	Virh Long Virh Long Virh Long	96357 96357 9 6357
C Troop 3d SC Det (RL) 371st TC Det (KD)	Vinh Long Vinh Long Vinh Long	96357 96357 96357
D Troop	Vinh Long	96357
D Troop, 3d Sodn, 5th Air Cav	Vinh Long (Attached)	9635?

NOTE: /11 Aviation Detackments on this listing are assigned to the 165th Aviation Group (Combat) and further attached to Brigade units or other Commands as indicated.

INCLASSIFIED
Security Classification DOCUMENT CONTROL DATA - R & D M. HEPORT SECURITY CLASSIFICA" OF CONFIDENTIAL HQ. DACSFOR, DA, Washington, D.C. 20310 S. BEPORT TITLE Operational Report-Lessons Learned, HQ, 1st Aviation Brigade Experiences of unit engaged in counterinsurgency operations, 1 Feb to 30 Apr 70. CG, lat Aviation Brigade M. TOTAL NO. OF PAGES 76. NO. OF REFS 15 May 1970 43 S. ORIGINATOR'S REPORT NUMBER(S) & PROJECT 40. N/A 702215 b. OTHER REPORT NOISI (Any other numbers that may be easigned this report) 12 DISTRIBUTION STATEMENT 12. SPONSORING MILITARY ACTIVITY II. SUPPLEMENTARY NOTES OACSFOR, DA, Washington, D.C. 20310 N/A IS. ABSTRACT

DD .::..1473

UNCLASSIFIED

Socurity Classification